

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਇਮਰੀ ਮੰਡਲ ਭ ਤੋ ਮ ਸਾਖਾ
ਹੁਸ਼ਿਆਰਪੁਰ :

ਵੱਲ

The Principal
Delhi International School
Chabewal Hoshiarpur

ਨੰਬਰ 309 ਮਿਤੀ 09-05-23


ਵਿਸ਼ਾ :- ਇਸ਼ੂ ਆਫ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ 2023-24

ਹਵਾਲਾ :- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ Application ਮਿਤੀ

ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ~~ਪਿਠ~~ ਉਪ
ਮੰਡਲ ਨੰ: 2 ਹੁਸ਼ਿਆਰਪੁਰ ਵਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋ ਠੀਕ ਠਾਕ ਲੱਗਦੀ ਹੈ
ਅਤੇ ਸਾਲ 2023-24 ਲਈ ਸੁਰੱਖਿਆਤ ਪਾਈ ਗਈ ਹੈ ਅੱਗੇ ਤੋਂ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ
ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ :-

1. ਬਿਲਡਿੰਗ ਦੀਆਂ ਛੱਤਾਂ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ ।
2. ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇਤ ਵਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੋਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ ।
3. ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜ਼ੂਰੀ ਇਸ ਮਹਿਕਮੇ ਪਾਸੋਂ ਲਈ ਜਾਵੇ ।

ਨੱਥੀ / ਨਕਸ਼ਾ ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਇਮਰੀ ਮੰਡਲ ਭ ਤੋ ਮ ਸਾਖਾ
ਹੁਸ਼ਿਆਰਪੁਰ

ਪਿੱਠ ਅੰਕਣ ਨੰ: ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਇਮਰੀ ਮੰਡਲ ਨੰ: 2

ਹੁਸ਼ਿਆਰਪੁਰ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ : 462 ਮਿਤੀ 9-5-23 ਦੇ ਹਵਾਲੇ ਅਧੀਨ

ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ।

ਨੱਥੀ / X

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਇਮਰੀ ਮੰਡਲ ਭ ਤੋ ਮ ਸਾਖਾ
ਹੁਸ਼ਿਆਰਪੁਰ

(English Translation of Building Safety Certificate)

From

Executive Engineer,
Provincial Division B & R,
Hoshiarpur.

To

The principal
Delhi International School
Chabbewal, Hoshiarpur

Number: 309

Date: 09-05-2023

Subject: - Issuance of Building Safety Certificate for the year 2023-24.

Reference: your letter no Application dated: _____

The inspection of the above school building has been done by Sub Divisional Engineer Provincial Sub Division No: 2 Hoshiarpur and this building looks sound and is found to be safe for the year 2023-24. Further special attention should be paid to the following instructions: -

1. Water should not be allowed to stand on the roofs and around the building.
2. If there is any kind of crack in the building then it should be vacated immediately and its repair should be done immediately.
3. In addition to the new map, if you want to do any additional construction, then its approval should be taken from this department.

Appendix / Map

Executive Engineer
Provincial Division B & R Branch
Hoshiarpur

Back number no.

Date:

The above is copied to Sub Divisional Engineer Provincial Sub Division No. 2 Hoshiarpur vide his letter No.: 482 dated: 09-05-2023 is sent.

Appendix/ X


Chairman
Delhi International School
Hoshiarpur


Principal
Delhi International School
Hoshiarpur

Executive Engineer
Provincial Division B & R Branch
Hoshiarpur